



****PUBLIC NOTICE****

for Sunset Bay
Public Water System

CHANGE IN WATER DISINFECTANT

On April 16, 2025, the Sunset Bay neighborhood will be changing the disinfectant that we use from chlorine to chloramines. This change is intended to benefit our customers by reducing the levels of disinfection byproducts (DBPs) like trihalomethanes (TTHM) in the system, while still providing protection from waterborne disease.

However, the change to chloramines can cause problems to persons dependent on **dialysis machines**. A condition known as hemolytic anemia can occur if the disinfectant is not completely removed from the water that is used for the dialysate. Consequently, the pretreatment scheme used for the dialysis units must include some means, such as a charcoal filter, for removing the chloramine prior to this date. Medical facilities should also determine if additional precautions are required for other medical equipment.

In addition, chloraminated water may be toxic to fish. **If you have a fish tank**, please make sure that the chemicals or filters that you are using are designed for use in water that has been treated with chloramines. You may also need to change the type of filter that you use for the fish tank.

If you believe this change might affect you, or if you have questions concerning this matter, you may contact NextEra Water Texas at (866) 639-9287.

This notice is from NextEra Water Texas.

State Water System ID#: TX0040055

Date distributed: 3/31/2025



****AVISO PÚBLICO****

del Sistema Público de Agua
de Sunset Bay

CAMBIO EN EL DESINFECTANTE DEL AGUA

El 16 de abril de 2025, el vecindario de Sunset Bay cambiará el desinfectante que usamos de cloro a cloraminas. Este cambio tiene como objetivo beneficiar a nuestros clientes al reducir los niveles de subproductos de desinfección (DBPs) como los trihalometanos (TTHM) en el sistema, al mismo tiempo que proporciona protección contra enfermedades transmitidas por el agua. Sin embargo, el cambio a cloraminas puede causar problemas a las personas que dependen de máquinas de diálisis. Una condición conocida como anemia hemolítica puede ocurrir si el desinfectante no se elimina completamente del agua que se usa para el dializado. Por lo tanto, el esquema de pretratamiento utilizado para las unidades de diálisis debe incluir algún medio, como un filtro de carbón, para eliminar la cloramina antes de esta fecha. Las instalaciones médicas también deben determinar si se requieren precauciones adicionales para otros equipos médicos.

Además, el agua cloraminada puede ser tóxica para los peces. Si tiene un acuario, asegúrese de que los productos químicos o filtros que está utilizando estén diseñados para su uso en agua tratada con cloraminas. Es posible que también necesite cambiar el tipo de filtro que usa para el acuario.

Si cree que este cambio podría afectarle, o si tiene preguntas sobre este asunto, puede contactar a NextEra Water Texas al (866) 639-9287.

Este aviso es de NextEra Water Texas.

ID del Sistema de Agua Estatal: TX0040055

Fecha de distribución: 31/3/2025